

OnShape Keyboard Shortcuts

Drawings

shift	z	Zoom in	
	z	Zoom out	
	f	Zoom to fit	
	w	Zoom to window	
	p	Projected view	
	d	Dimension	
	m	Maximum/minimum dimension	
shift	r	Radial dimension	
shift	d	Diameter dimension	
shift	q	Quad & Mid snap points	
	n	Note	
ctrl	q	Update drawing	
	l	Line	
ctrl	s	Display sheet menu	
	pg dn	Next sheet	
	pg up	Previous sheet	
	home	First sheet	
	end	Last sheet	
alt	LMB	drag	Copy annotation

Assembly

shift		Lock mate inference
ctrl / ⌘	c	Copy
ctrl / ⌘	v	Paste
	m	Mate
ctrl	m	Mate connector
	i	Insert dialog
shift	s	Snap mode
	h	Show mates mode
	a	Flip primary axis
	q	Reorient secondary axis
	j	Hide/show mates
	k	Hide/show mate connectors

General

shift	?	Keyboard shortcuts
ctrl / ⌘	z	Undo
ctrl y	⌘ shift y	Redo
	delete	Delete selection
	space bar	Clear selection
	`	Select other
shift	n	Rename selection
	esc	Cancel command
	enter	Accept command
shift	enter	Accept & repeat command
alt	c	Search tools
	s	Shortcut toolbars
shift	click	Open in new window
ctrl / ⌘	click	Open in new tab
ctrl	u	Feedback/Report a bug
alt	t	Search tabs
ctrl	space bar	Quick tab switching

Sketch

shift		Suppress inferencing
	l	Line
	g	Corner rectangle
	r	Center point rectangle
	c	Center point circle
	a	3 point arc
shift	f	Fillet
	m	Trim
	x	Extend
	o	Offset
	u	Use
	d	Dimension
	i	Coincident
	b	Parallel
	t	Tangent
	h	Horizontal
	v	Vertical
	e	Equal
	q	Toggle construction

Part Studio

shift	s	Sketch
shift	e	Extrude
shift	f	Fillet
ctrl	m	Mate connector
shift		Lock mate inference
	a	Flip primary axis
	q	Reorient secondary axis
	k	Hide/show mate connectors

3D view

	shift	z	Zoom in
rt a bug		z	Zoom out
		f	Zoom to fit
ing		w	Zoom to window
		← → ↑ ↓	Rotate
	shift	← → ↑ ↓	Precision rotate
ctrl	shift	← → ↑ ↓	Pan
	shift	1	Front view
	shift	2	Back view
	shift	3	Left view
	shift	4	Right view
	shift	5	Top view
	shift	6	Bottom view
	shift	7	Isometric view
		n	View normal to
		p	Hide/show planes
	shift	p	Hide all construction
	shift	v	Named views
	shift	x	Section view
		y	Hide selected part
	shift	y	Show selected part
	shift	t	Make transparent
	shift	i	Isolate